

**Flood Control Project Maintenance
Levee Inspections**

Fall 2013 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including USACE Erosion Survey

Sacramento River Basin

RD0765 Reclamation District No. 0765 Glide	Overall LMA Rating	Total LMA Miles						
	U	1.74						
Rated Item	Maintenance Deficiency				Enforcement		Design & System Obsolescence	
	M Miles	U Miles	M + 4U Miles	Threshold %	M Miles	U Miles	M Miles	U Miles
<i>Earthen Levee</i>								
Vegetation	0.04	0.05	0.24	13.79%				
Trim / Thin Trees	0.83	0.17	1.51	86.78%				
Encroachments	0.03	0.01	0.07	4.02%	0.33	0.06		
Slope Stability	0.04		0.04	2.30%				
Erosion / Bank Caving		0.01	0.04	2.30%				
Operations & Maintenance Manuals	0.02		0.02	1.15%				
Emergency Supplies & Equipment	0.02		0.02	1.15%				
Flood Preparedness & Training	0.02		0.02	1.15%				
LMA Totals:	0.99	0.24	1.95	112.07%	0.33	0.06	0.00	0.00

**Flood Control Project Maintenance
Levee Inspections
LMA District Cover Sheet
Fall 2013 Levee Inspection Results**

Reclamation District No. 0765 Glide

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)			U	

** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

* **SPRING INSPECTIONS:** Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports. This rating is not intended to be an indication of risk.

Comments

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2013 Levee Inspection Results

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles
Unit No. 01 Sacramento River	Right	1.74

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			U	
Date of Inspection	03/05/2013 - 03/05/2013		10/16/2013 - 10/21/2013	
DWR Inspector	Richard Willoughby		Richard Willoughby	
Accompanied By	Everett Lovejoy RD765		Everett Lovejoy RD 765	

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2013

Reclamation District No. 0765 Glide

Waterway		Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River		Right	1.74	10/16/2013 10/21/2013	Richard Willoughby

LMR No.	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1			Earthen Levee	Emergency Supplies & Equipment	LS	M Ma		°	°	18
								DWR ID: DWR_RD0765_01_s_2013_18		
2			Earthen Levee	Operations & Maintenance Manuals	LS	M Ma		°	°	44
								DWR ID: DWR_RD0765_01_s_2012_44		
3			Earthen Levee	Flood Preparedness & Training	LS	M Ma		°	°	46
								DWR ID: DWR_RD0765_01_s_2012_46		
4	0.00	0.11	Earthen Levee	Encroachments	LS	M En	FE : Fence	38.502962 ° -121.560112 °	38.501373 ° -121.560402 °	12
								DWR ID: DWR_RD0765_01_s_2012_12		
5	0.05	0.05	Earthen Levee	Trim / Thin Trees	LS	M Ma	T1 : Trim trees to at least five feet above ground level.	38.502253 ° -121.560192 °	38.502253 ° -121.560192 °	3 Y
								DWR ID: DWR_RD0765_01_s_2012_3		
6	0.09	0.09	Earthen Levee	Trim / Thin Trees	WSA/W	M Ma	T1 : Trim trees to at least five feet above ground level.	38.501650 ° -121.560290 °	38.501650 ° -121.560290 °	27
								DWR ID: DWR_RD0765_01_s_2012_27		
7	0.12	0.19	Earthen Levee	Trim / Thin Trees	LS	M Ma	T3 : Trim and thin trees to allow visibility of the ground and room to flood fight.	38.501215 ° -121.560432 °	38.500271 ° -121.560434 °	28 Y
								DWR ID: DWR_RD0765_01_s_2012_28		
8	0.13	0.13	Earthen Levee	Trim / Thin Trees	LS	M Ma	T1 : Trim trees to at least five feet above ground level.	38.501181 ° -121.560410 °	38.501181 ° -121.560410 °	45
								DWR ID: DWR_RD0765_01_f_2013_45		
9	0.14	0.14	Earthen Levee	Vegetation	LS	M Ma	V4 : Elderberries are blocking visibility and flood fight capability.	38.500928 ° -121.560431 °	38.500928 ° -121.560431 °	22 Y
								DWR ID: DWR_RD0765_01_s_2012_22		
10	0.19	0.35	Earthen Levee	Trim / Thin Trees	LS	M Ma	T1 : Trim trees to at least five feet above ground level.	38.500343 ° -121.560507 °	38.498032 ° -121.560337 °	14
								DWR ID: DWR_RD0765_01_s_2012_14		
11	0.21	0.21	Earthen Levee	Trim / Thin Trees	WSA/W	M Ma	T1 : Trim trees to at least five feet above ground level.	38.500018 ° -121.560457 °	38.500018 ° -121.560457 °	25
								DWR ID: DWR_RD0765_01_s_2012_25		
12	0.24	0.24	Earthen Levee	Vegetation	LS	M Ma	V2 : Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: Wild berryvines on landside slope.	38.499530 ° -121.560490 °	38.499530 ° -121.560490 °	49 Y
								DWR ID: DWR_RD0765_01_s_2013_49		
13	0.25	0.28	Earthen Levee	Trim / Thin Trees	WS	U Ma	T2 : Thin trees to allow visibility of the ground and room to flood fight.	38.499405 ° -121.560445 °	38.499042 ° -121.560430 °	11 Y
								DWR ID: DWR_RD0765_01_s_2012_11		
14	0.26	0.26	Earthen Levee	Encroachments	LS	M En	GA : Garbage Inspector Comments: Trash dump on landward shoulder.	38.499177 ° -121.560488 °	38.499177 ° -121.560488 °	54 Y
								DWR ID: DWR_RD0765_01_f_2013_54		

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2013

Reclamation District No. 0765 Glide

Waterway		Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River		Right	1.74	10/16/2013 10/21/2013	Richard Willoughby

LMIR No.	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
15	0.31	0.31	Earthen Levee	Vegetation	LS	M Ma	V2 : Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: Wild berryvines on landside toe.	38.498516 ° -121.560463 °	38.498516 ° -121.560463 °	31
DWR ID: DWR_RD0765_01_f_2012_31										
16	0.32	0.32	Earthen Levee	Trim / Thin Trees	WS	M Ma	T2 : Thin trees to allow visibility of the ground and room to flood fight.	38.498453 ° -121.560360 °	38.498453 ° -121.560360 °	23
DWR ID: DWR_RD0765_01_s_2012_23										
17	0.41	0.41	Earthen Levee	Trim / Thin Trees	LS	M Ma	T1 : Trim trees to at least five feet above ground level.	38.497196 ° -121.560147 °	38.497196 ° -121.560147 °	21
DWR ID: DWR_RD0765_01_s_2012_21										
18	0.41	0.52	Earthen Levee	Trim / Thin Trees	WS	M Ma	T2 : Thin trees to allow visibility of the ground and room to flood fight.	38.497125 ° -121.560087 °	38.495648 ° -121.559391 °	24
DWR ID: DWR_RD0765_01_s_2012_24										
19	0.41	0.41	Earthen Levee	Vegetation	LS	U Ma	V2 : Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: Wild berryvines on landside toe.	38.497069 ° -121.560106 °	38.497069 ° -121.560106 °	47 Y
DWR ID: DWR_RD0765_01_f_2012_47										
20	0.43	0.47	Earthen Levee	Trim / Thin Trees	LS	M Ma	T3 : Trim and thin trees to allow visibility of the ground and room to flood fight.	38.496792 ° -121.560026 °	38.496321 ° -121.559842 °	32 Y
DWR ID: DWR_RD0765_01_s_2012_32										
21	0.47	0.47	Earthen Levee	Encroachments	LS	M Ma	GA : Garbage Inspector Comments: Trash dump on landside slope.	38.496235 ° -121.559796 °	38.496235 ° -121.559796 °	55 Y
DWR ID: DWR_RD0765_01_f_2013_55										
22	0.48	0.50	Earthen Levee	Vegetation	LS	U Ma	V2 : Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: District removed some of the wild growth on landside slope and toe.	38.496217 ° -121.559788 °	38.495855 ° -121.559586 °	33 Y
DWR ID: DWR_RD0765_01_s_2012_33										
23	0.54	0.71	Earthen Levee	Encroachments	LS	M En	DT : Ditch Inspector Comments: Irrigation ditch at landward toe.	38.495350 ° -121.559300 °	38.493303 ° -121.557620 °	56
DWR ID: DWR_RD0765_01_f_2013_56										
24	0.54	0.64	Earthen Levee	Trim / Thin Trees	LS	A/W Ma	T1 : Trim trees to at least five feet above ground level.	38.495347 ° -121.559291 °	38.494204 ° -121.558313 °	34
DWR ID: DWR_RD0765_01_s_2012_34										
25	0.57	0.60	Earthen Levee	Trim / Thin Trees	WS	M Ma	T1 : Trim trees to at least five feet above ground level.	38.495035 ° -121.559027 °	38.494642 ° -121.558697 °	10
DWR ID: DWR_RD0765_01_s_2012_10										
26	0.69	0.73	Earthen Levee	Trim / Thin Trees	LS	M Ma	T1 : Trim trees to at least five feet above ground level.	38.493596 ° -121.557832 °	38.493077 ° -121.557451 °	35
DWR ID: DWR_RD0765_01_s_2012_35										
27	0.71	0.71	Earthen Levee	Trim / Thin Trees	WS	M Ma	T1 : Trim trees to at least five feet above ground level.	38.493392 ° -121.557640 °	38.494171 ° -121.558253 °	15
DWR ID: DWR_RD0765_01_s_2012_15										
28	0.76	0.80	Earthen Levee	Vegetation	LS	A/W Ma	V2 : Remove the wild growth other than native grasses from the levee slopes.	38.492713 ° -121.557224 °	38.492176 ° -121.556893 °	50 Y
DWR ID: DWR_RD0765_01_s_2013_50										

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2013

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	10/16/2013 10/21/2013	Richard Willoughby

LMIR No.	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
29	0.78	0.81	Earthen Levee	Trim / Thin Trees	LS	M Ma	T3 : Trim and thin trees to allow visibility of the ground and room to flood fight.	38.492392 ° -121.557026 °	38.492034 ° -121.556820 °	36 Y
DWR ID: DWR_RD0765_01_s_2012_36										
30	0.87	0.99	Earthen Levee	Trim / Thin Trees	LS	U Ma	T1 : Trim trees to at least five feet above ground level.	38.491283 ° -121.556360 °	38.489771 ° -121.555451 °	17 Y
DWR ID: DWR_RD0765_01_s_2012_17										
31	0.97	0.97	Earthen Levee	Vegetation	LS	M Ma	V2 : Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: Dense berryvines on landside slope.	38.489962 ° -121.555573 °	38.489962 ° -121.555573 °	81 Y
DWR ID: DWR_RD0765_01_s_2012_81										
32	0.99	0.99	Earthen Levee	Encroachments	LS	M En	DT : Ditch Inspector Comments: Ditch has been in place for several years.	38.489653 ° -121.555399 °	38.489653 ° -121.555399 °	51 Y
DWR ID: DWR_RD0765_01_s_2013_51										
33	0.99	1.15	Earthen Levee	Trim / Thin Trees	WS	M Ma	T1 : Trim trees to at least five feet above ground level.	38.489664 ° -121.555370 °	38.487617 ° -121.554200 °	6 Y
DWR ID: DWR_RD0765_01_f_2012_6										
34	1.02	1.02	Earthen Levee	Vegetation	LS	U Ma	V7 : Trees / Woody Vegetation Inspector Comments: Fig trees on landside slope	38.489283 ° -121.555223 °	38.489283 ° -121.555223 °	40 Y
DWR ID: DWR_RD0765_01_s_2012_40										
35	1.04	1.04	Earthen Levee	Vegetation	LS	A/W En	V6 : Landscaping Inspector Comments: Cactus at landside toe.	38.489036 ° -121.555054 °	38.489036 ° -121.555054 °	16 Y
DWR ID: DWR_RD0765_01_f_2012_16										
36	1.08	1.08	Earthen Levee	Trim / Thin Trees	LS	M Ma	T3 : Trim and thin trees to allow visibility of the ground and room to flood fight.	38.488503 ° -121.554757 °	38.488503 ° -121.554757 °	37 Y
DWR ID: DWR_RD0765_01_s_2012_37										
37	1.10	1.16	Earthen Levee	Trim / Thin Trees	LS	M Ma	T1 : Trim trees to at least five feet above ground level.	38.488279 ° -121.554615 °	38.487465 ° -121.554117 °	38 Y
DWR ID: DWR_RD0765_01_s_2012_38										
38	1.15	1.15	Earthen Levee	Vegetation	LS	U Ma	V2 : Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: Wild berryvines at landside toe.	38.487645 ° -121.554233 °	38.487645 ° -121.554233 °	48 Y
DWR ID: DWR_RD0765_01_f_2012_48										
39	1.16	1.16	Earthen Levee	Trim / Thin Trees	WS	M Ma	T1 : Trim trees to at least five feet above ground level.	38.487473 ° -121.554080 °	38.487473 ° -121.554080 °	9 Y
DWR ID: DWR_RD0765_01_s_2012_9										
40	1.19	1.22	Earthen Levee	Encroachments	LS	M En	BU : Building	38.487127 ° -121.553910 °	38.486702 ° -121.553652 °	43 Y
DWR ID: DWR_RD0765_01_s_2012_43										
41	1.32	1.34	Earthen Levee	Slope Stability	WS	M Ma	S1 : Repair slope instability. Inspector Comments: Slope damage caused by tractor working on waterward slope.	38.485485 ° -121.552931 °	38.485218 ° -121.552772 °	39 Y
DWR ID: DWR_RD0765_01_f_2013_39										
42	1.32	1.35	Earthen Levee	Trim / Thin Trees	LS	A/W Ma	T1 : Trim trees to at least five feet above ground level.	38.485280 ° -121.552860 °	38.485002 ° -121.552687 °	26 Y
DWR ID: DWR_RD0765_01_s_2012_26										

* Location	** Rating	+ Issue Type
LS : Land Side	A : Acceptable	N : Not Inspected/Rated
WS : Water Side	M : Minimally Acceptable	C : Corrected
CR : Crown	U : Unacceptable	A/W : Acceptable but Monitor & Maintain
		Ma : Maintenance Deficiency
		Ob : Design & System Obsolescence
		En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2013

Reclamation District No. 0765 Glide

Waterway		Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River		Right	1.74	10/16/2013 10/21/2013	Richard Willoughby

LMR No.	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
43	1.33	1.33	Earthen Levee	Encroachments	WS En	C	TR : Tree or limb Inspector Comments: Downed tree on waterside slope.	38.485245 ° -121.552807 °	38.485245 ° -121.552807 °	20
DWR ID: DWR_RD0765_01_s_2012_20										
44	1.36	1.36	Earthen Levee	Vegetation	WSA/W Ma	V2	Remove the wild growth other than native grasses from the levee slopes.	38.484877 ° -121.552540 °	38.484877 ° -121.552540 °	7 Y
DWR ID: DWR_RD0765_01_s_2012_7										
45	1.41	1.41	Earthen Levee	Trim / Thin Trees	WS Ma	M	T1 : Trim trees to at least five feet above ground level.	38.484316 ° -121.552115 °	38.484316 ° -121.552115 °	4
DWR ID: DWR_RD0765_01_s_2012_4										
46	1.43	1.43	Earthen Levee	Encroachments	LS Ma	M	TR : Tree or limb Inspector Comments: Downed tree limbs on landward toe.	38.483987 ° -121.551964 °	38.483987 ° -121.551964 °	57
DWR ID: DWR_RD0765_01_f_2013_57										
47	1.44	1.47	Earthen Levee	Trim / Thin Trees	WS Ma	M	T2 : Thin trees to allow visibility of the ground and room to flood fight.	38.483925 ° -121.551845 °	38.483530 ° -121.551587 °	5 Y
DWR ID: DWR_RD0765_01_s_2012_5										
48	1.46	1.46	Earthen Levee	Trim / Thin Trees	LS A/W Ma	M	T1 : Trim trees to at least five feet above ground level.	38.483640 ° -121.551727 °	38.483640 ° -121.551727 °	41
DWR ID: DWR_RD0765_01_s_2012_41										
49	1.48	1.48	Earthen Levee	Slope Stability	LS Ma	M	S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible. Inspector Comments: Slope damage on landward slope.	38.483379 ° -121.551545 °	38.483379 ° -121.551545 °	58 Y
DWR ID: DWR_RD0765_01_f_2013_58										
50	1.48	1.48	Earthen Levee	Slope Stability	WS Ma	M	S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible. Inspector Comments: Slope damage caused by tractor.	38.483353 ° -121.551457 °	38.483353 ° -121.551457 °	19 Y
DWR ID: DWR_RD0765_01_f_2013_19										
51	1.50	1.51	Earthen Levee	Trim / Thin Trees	LS Ma	M	T1 : Trim trees to at least five feet above ground level.	38.483170 ° -121.551367 °	38.482965 ° -121.551265 °	42
DWR ID: DWR_RD0765_01_s_2012_42										
52	1.52	1.73	Earthen Levee	Vegetation	WSA/W Ma	V2	Remove the wild growth other than native grasses from the levee slopes.	38.482893 ° -121.551121 °	38.480257 ° -121.549458 °	1 Y
DWR ID: DWR_RD0765_01_s_2012_1										
53	1.54	1.54	Earthen Levee	Trim / Thin Trees	LS Ma	U	T1 : Trim trees to at least five feet above ground level. Inspector Comments: Dense berryvines and dense trees on landward slope.	38.482665 ° -121.551036 °	38.482665 ° -121.551036 °	29 Y
DWR ID: DWR_RD0765_01_s_2012_29										
54	1.54	1.54	Earthen Levee	Encroachments	WS Ma	C	GA : Garbage	38.482610 ° -121.550937 °	38.482610 ° -121.550937 °	2
DWR ID: DWR_RD0765_01_f_2012_2										
55	1.56	1.56	Earthen Levee	Encroachments	LS Ma	M	PR : Prunings	38.482402 ° -121.550867 °	38.482402 ° -121.550867 °	59 Y
DWR ID: DWR_RD0765_01_f_2013_59										
56	1.56	1.56	Earthen Levee	Erosion / Bank Caving	WS Ma	U	E2 : Schedule repair of erosion site prior to the next inspection. Inspector Comments: Erosion located around metal walkway on waterward shoulder and slope.	38.482414 ° -121.550804 °	38.482414 ° -121.550804 °	8 Y
DWR ID: DWR_RD0765_01_f_2013_8										

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2013

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	10/16/2013 10/21/2013	Richard Willoughby

LMR No.	Levee Mile		Category	Item	* Location	+ Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
57	1.57	1.63	Earthen Levee	Encroachments	LS En	U	DT : Ditch Inspector Comments: Old Irrigation ditch at landward toe.	38.482300 ° -121.550808 °	38.481482 ° -121.550283 °	60 Y
DWR ID: DWR_RD0765_01_f_2013_60										
58	1.67	1.67	Earthen Levee	Trim / Thin Trees	WS	M Ma	T1 : Trim trees to at least five feet above ground level.	° °	38.480892 ° -121.549654 °	53
DWR ID: DWR_RD0765_01_s_2013_53										
59	1.69	1.69	Earthen Levee	Encroachments	WS Ma	C	GA : Garbage Inspector Comments: District removed trash.	38.480770 ° -121.549514 °	38.480895 ° -121.549556 °	30
DWR ID: DWR_RD0765_01_s_2012_30										
60	1.69	1.70	Earthen Levee	Encroachments	WS Ma	U	PR : Prunings Inspector Comments: Large tree branch on waterward slope.	38.480763 ° -121.549581 °	38.480632 ° -121.549543 °	13 Y
DWR ID: DWR_RD0765_01_s_2012_13										
61	1.71	1.72	Earthen Levee	Trim / Thin Trees	WS	U Ma	T1 : Trim trees to at least five feet above ground level.	38.480519 ° -121.549513 °	38.480164 ° -121.549445 °	52 Y
DWR ID: DWR_RD0765_01_s_2013_52										

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2013

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	10/16/2013 10/21/2013	Richard Willoughby

Levee Mile Report Line	5
Start Levee Mile	0.05
End Levee Mile	0.05
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking north (upstream) at trees on landside slope.	
richard_f_20130930_736.JPG	



Levee Mile Report Line	7
Start Levee Mile	0.12
End Levee Mile	0.19
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking west at trees on landside toe.	
richard_f_20130930_755.jpg	



Levee Mile Report Line	7
Start Levee Mile	0.12
End Levee Mile	0.19
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking downstream (south) at trees on landside slope & toe.	
richard_f_20130930_756.jpg	



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2013

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	10/16/2013 10/21/2013	Richard Willoughby

Levee Mile Report Line	9
Start Levee Mile	0.14
End Levee Mile	0.14
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Looking northwest at dense vegetation on landside slope.	
richard_f_20130930_753.JPG	



Levee Mile Report Line	12
Start Levee Mile	0.24
End Levee Mile	0.24
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Looking at wild berryvines or wild roses on landside slope and toe.	
richard_f_20130930_775.JPG	



Levee Mile Report Line	13
Start Levee Mile	0.25
End Levee Mile	0.28
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking northeast at overgrown trees on waterside slope.	
richard_f_20130930_741.jpg	



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2013

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	10/16/2013 10/21/2013	Richard Willoughby

Levee Mile Report Line	13
Start Levee Mile	0.25
End Levee Mile	0.28
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking north at dense trees on waterside slope from fall 2010 inspection.	
richard_f_20130930_742.jpg	



Levee Mile Report Line	13
Start Levee Mile	0.25
End Levee Mile	0.28
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking upstream (north) at dense vegetation and trees from 2011 spring inspection.	
richard_f_20130930_743.jpg	



Levee Mile Report Line	13
Start Levee Mile	0.25
End Levee Mile	0.28
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking north (upstream) at dense trees on landside slope and shoulder. (Spring 2013)	
richard_f_20130930_744.JPG	



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2013

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	10/16/2013 10/21/2013	Richard Willoughby

Levee Mile Report Line	13
Start Levee Mile	0.25
End Levee Mile	0.28
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking south (downstream) at dense trees on landside slope and shoulder. (Spring 2013)	
richard_f_20130930_745.JPG	



Levee Mile Report Line	14
Start Levee Mile	0.26
End Levee Mile	0.26
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Looking southwest at garbage on landward shoulder and slope.	
richard_f_20131024_108.JPG	



Levee Mile Report Line	16
Start Levee Mile	0.32
End Levee Mile	0.32
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking north (upstream) at untrimmed trees on waterside shoulder and slope.	
richard_f_20130930_754.JPG	



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2013

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	10/16/2013 10/21/2013	Richard Willoughby

Levee Mile Report Line	19
Start Levee Mile	0.41
End Levee Mile	0.41
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Looking west at dense berryvines on landside toe.	
richard_f_20130930_773.JPG	



Levee Mile Report Line	20
Start Levee Mile	0.43
End Levee Mile	0.47
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking southwest at dense vegetation on landside slope and toe.	
richard_f_20130930_762.jpg	



Levee Mile Report Line	21
Start Levee Mile	0.47
End Levee Mile	0.47
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Looking west at garbage on landward slope and toe.	
richard_f_20131024_122.JPG	



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2013

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	10/16/2013 10/21/2013	Richard Willoughby

Levee Mile Report Line	22
Start Levee Mile	0.48
End Levee Mile	0.50
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Looking northwest at trees on landside toe from 2010 fall inspection.

richard_f_20130930_763.jpg



Levee Mile Report Line	22
Start Levee Mile	0.48
End Levee Mile	0.50
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Looking downstream (south) at trees on landside slope & toe.

richard_f_20130930_764.jpg



Levee Mile Report Line	22
Start Levee Mile	0.48
End Levee Mile	0.50
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Looking downstream (southwest) at dense vegetation on landside slope.

richard_f_20130930_765.jpg



<p>* Location</p> <p>LS : Land Side WS : Water Side CR : Crown</p>	<p>** Rating</p> <p>A : Acceptable M : Minimally Acceptable U : Unacceptable</p>	<p>N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain</p>	<p>+ Issue Type</p> <p>Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement</p>
---	---	--	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2013

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	10/16/2013 10/21/2013	Richard Willoughby

Levee Mile Report Line	22
Start Levee Mile	0.48
End Levee Mile	0.50
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Looking upstream (northwest) at dense vegetation on landside slope.	
richard_f_20130930_766.jpg	



Levee Mile Report Line	22
Start Levee Mile	0.48
End Levee Mile	0.50
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Looking southwest at dense vegetation on landside slope and toe.	
richard_f_20130930_767.JPG	



Levee Mile Report Line	28
Start Levee Mile	0.76
End Levee Mile	0.80
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Looking northwest at vegetation on landside slope.	
richard_f_20130930_776.JPG	



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2013

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	10/16/2013 10/21/2013	Richard Willoughby

Levee Mile Report Line	30
Start Levee Mile	0.87
End Levee Mile	0.99
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking downstream (south) at dense trees on landside slope and toe.	
richard_f_20130930_748.jpg	



Levee Mile Report Line	30
Start Levee Mile	0.87
End Levee Mile	0.99
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking upstream (north) at dense trees on landside slope and toe.	
richard_f_20130930_749.jpg	



Levee Mile Report Line	30
Start Levee Mile	0.87
End Levee Mile	0.99
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking south at dense trees on landside shoulder and slope. (November 2011)	
richard_f_20130930_750.jpg	



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2013

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	10/16/2013 10/21/2013	Richard Willoughby

Levee Mile Report Line	30
Start Levee Mile	0.87
End Levee Mile	0.99
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking southwest at dense trees on landside slope and toe spring 2012.	
richard_f_20130930_751.jpg	



Levee Mile Report Line	30
Start Levee Mile	0.87
End Levee Mile	0.99
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking southwest at dense vegetation on landward slope.	
richard_f_20131024_115.JPG	



Levee Mile Report Line	31
Start Levee Mile	0.97
End Levee Mile	0.97
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Looking west at dense berryvines and wildroses on landside shoulder and slope. (November 2011)	
richard_f_20130930_779.jpg	



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2013

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	10/16/2013 10/21/2013	Richard Willoughby

Levee Mile Report Line	31
Start Levee Mile	0.97
End Levee Mile	0.97
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Looking northwest at vines on landside toe spring 2012.	
richard_f_20130930_780.jpg	



Levee Mile Report Line	31
Start Levee Mile	0.97
End Levee Mile	0.97
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Looking west at trimmed trees on landward slope.	
richard_f_20131024_118.JPG	



Levee Mile Report Line	32
Start Levee Mile	0.99
End Levee Mile	0.99
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Looking southwest at irrigation ditch on landward toe.	
richard_f_20131024_119.JPG	



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2013

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	10/16/2013 10/21/2013	Richard Willoughby

Levee Mile Report Line	34
Start Levee Mile	1.02
End Levee Mile	1.02
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Looking southwest at fig trees and other trees on landside slope and toe.	
richard_f_20130930_771.jpg	



Levee Mile Report Line	35
Start Levee Mile	1.04
End Levee Mile	1.04
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Looking west at cactus at landside toe.	
richard_f_20130930_747.JPG	



Levee Mile Report Line	36
Start Levee Mile	1.08
End Levee Mile	1.08
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking downstream (south) at trees on landside slope & toe from 2010 fall inspection.	
richard_f_20130930_768.jpg	



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2013

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	10/16/2013 10/21/2013	Richard Willoughby

Levee Mile Report Line	36
Start Levee Mile	1.08
End Levee Mile	1.08
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking west at trees on landside slope & toe.	
richard_f_20130930_769.jpg	



Levee Mile Report Line	36
Start Levee Mile	1.08
End Levee Mile	1.08
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking downstream (southwest) at dense trees on landside slope and toe.	
richard_f_20130930_770.jpg	



Levee Mile Report Line	36
Start Levee Mile	1.08
End Levee Mile	1.08
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking southwest at trees on landward slope.	
richard_f_20131024_120.JPG	



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2013

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	10/16/2013 10/21/2013	Richard Willoughby

Levee Mile Report Line	38
Start Levee Mile	1.15
End Levee Mile	1.15
Location	Land Side
Category	Earthen Levee
Item	Vegetation
Looking southwest at dense vegetation on landside slope and toe.	
richard_f_20130930_774.JPG	



Levee Mile Report Line	40
Start Levee Mile	1.19
End Levee Mile	1.22
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Looking northwest at buildings along landside toe.	
richard_f_20130930_772.jpg	



Levee Mile Report Line	41
Start Levee Mile	1.32
End Levee Mile	1.34
Location	Water Side
Category	Earthen Levee
Item	Slope Stability
Looking north at slope damage on waterward shoulder.	
richard_f_20131024_114.JPG	



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2013

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	10/16/2013 10/21/2013	Richard Willoughby

Levee Mile Report Line	44
Start Levee Mile	1.36
End Levee Mile	1.36
Location	Water Side
Category	Earthen Levee
Item	Vegetation
Looking upstream (north) at dense vegetation on waterside slope.	
richard_f_20130930_739.jpg	



Levee Mile Report Line	44
Start Levee Mile	1.36
End Levee Mile	1.36
Location	Water Side
Category	Earthen Levee
Item	Vegetation
Looking southeast at dense vegetation on waterside slope. (Fall Inspection 2012)	
richard_f_20130930_740.JPG	



Levee Mile Report Line	47
Start Levee Mile	1.44
End Levee Mile	1.47
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking upstream (north) at dense trees on waterside slope.	
richard_f_20130930_737.jpg	



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2013

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	10/16/2013 10/21/2013	Richard Willoughby

Levee Mile Report Line	47
Start Levee Mile	1.44
End Levee Mile	1.47
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees

Looking north at dense vegetation on waterside slope. (Fall Inspection 2012)

richard_f_20130930_738.JPG



Levee Mile Report Line	49
Start Levee Mile	1.48
End Levee Mile	1.48
Location	Land Side
Category	Earthen Levee
Item	Slope Stability

Looking west at slope damage on landward slope.

richard_f_20131024_117.JPG



Levee Mile Report Line	50
Start Levee Mile	1.48
End Levee Mile	1.48
Location	Water Side
Category	Earthen Levee
Item	Slope Stability

Looking southeast at slope damage on waterward slope.

richard_f_20131024_112.JPG



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2013

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	10/16/2013 10/21/2013	Richard Willoughby

Levee Mile Report Line	50
Start Levee Mile	1.48
End Levee Mile	1.48
Location	Water Side
Category	Earthen Levee
Item	Slope Stability
Looking southwest at slope damage on waterward slope.	
richard_f_20131024_113.JPG	



Levee Mile Report Line	52
Start Levee Mile	1.52
End Levee Mile	1.73
Location	Water Side
Category	Earthen Levee
Item	Vegetation
Looking south at dense trees and vegetation on waterside slope. (November 2011)	
richard_f_20130930_732.jpg	



Levee Mile Report Line	52
Start Levee Mile	1.52
End Levee Mile	1.73
Location	Water Side
Category	Earthen Levee
Item	Vegetation
Looking north at dense vegetation on waterside slope.	
richard_f_20130930_733.JPG	



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2013

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	10/16/2013 10/21/2013	Richard Willoughby

Levee Mile Report Line	52
Start Levee Mile	1.52
End Levee Mile	1.73
Location	Water Side
Category	Earthen Levee
Item	Vegetation
Looking northeast at dense vegetation on waterside slope.	
richard_f_20130930_734.JPG	



Levee Mile Report Line	53
Start Levee Mile	1.54
End Levee Mile	1.54
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking south at dense vegetation on landside shoulder and slope. (November 2011)	
richard_f_20130930_757.jpg	



Levee Mile Report Line	53
Start Levee Mile	1.54
End Levee Mile	1.54
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking south at dense vegetation on landside slope and toe spring 2012.	
richard_f_20130930_758.jpg	



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2013

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	10/16/2013 10/21/2013	Richard Willoughby

Levee Mile Report Line	53
Start Levee Mile	1.54
End Levee Mile	1.54
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking southwest at vegetation on landside slope and toe. (Fall Inspection 2012)	
richard_f_20130930_759.JPG	



Levee Mile Report Line	55
Start Levee Mile	1.56
End Levee Mile	1.56
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Looking west a prunings on landward berm.	
richard_f_20131024_116.JPG	



Levee Mile Report Line	56
Start Levee Mile	1.56
End Levee Mile	1.56
Location	Water Side
Category	Earthen Levee
Item	Erosion / Bank Caving
Looking south at erosion on waterward shoulder.	
richard_f_20131024_110.JPG	



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2013

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	10/16/2013 10/21/2013	Richard Willoughby

Levee Mile Report Line	56
Start Levee Mile	1.56
End Levee Mile	1.56
Location	Water Side
Category	Earthen Levee
Item	Erosion / Bank Caving
Looking west at erosion on waterward shoulder and slope.	
richard_f_20131024_111.JPG	



Levee Mile Report Line	57
Start Levee Mile	1.57
End Levee Mile	1.63
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Looking southwest at irrigation ditch on landward toe.	
richard_f_20131024_121.JPG	



Levee Mile Report Line	60
Start Levee Mile	1.69
End Levee Mile	1.70
Location	Water Side
Category	Earthen Levee
Item	Encroachments
Looking northeast at tree limbs on waterward slope.	
richard_f_20131024_109.JPG	



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2013

Reclamation District No. 0765 Glide

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Right	1.74	10/16/2013 10/21/2013	Richard Willoughby

Levee Mile Report Line	61
Start Levee Mile	1.71
End Levee Mile	1.72
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees
Looking north (upstream) at dense trees on landside slope.	
richard_f_20130930_778.JPG	



* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---